

BUILDING SAFETY CERTIFICATE




Rc. No: 020/EE/CD/HB/2026

Dated: 10-03-2026


It is certified that the existing building of Ryan school at Survey No. 318, 321, Dommara Pochampally Village, Gandimaisamma, Dundigal Mandal, Medchal- Malkajgiri District, Telangana – 500043 (address) is having block(s)/Floor(s) as per details below:

Details of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the block	1 Cellar + 1 Ground + 4 Upper Floors	NA	NA	NA	NA	NA

The building is occupied by Ryan School have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the Executive Engineer, Central Division , Telangana Housing Board on 07-03-2026 in the presence of the registered structural engineer of the educational institution and that the building is fit for running school with effect from 10-03-2026 for a period of 10 years in accordance with rule and subject to compliance of the specific conditions as appended.

Signature with Seal: Name: Designation: Name & Address of Department: 

To,
The Management
Ryan School
Survey No. 318, 321,
Dommara Pochampally Village,
Gandimaisamma , Dundigal Mandal
Medchal- Malkajgiri District, Telangana – 500043


Executive Engineer (Hq)
Central Division
Telangana Housing Board


PRINCIPAL
RYAN SCHOOL
Survey No: 321, Next to ORR Exit No: 5,
Gandimaisamma, Narsapur-Medak Highway,
Hyderabad-500 043.


Manager - Administration
RYAN SCHOOL
Survey No: 321, Next to ORR Exit No: 5,
Gandimaisamma, Narsapur-Medak Highway,
Hyderabad-500 043.